

## Doffing guide for Tornado

Do NOT remove the respirator hood until you have vacated the contaminated area.



1. Remove the hood using the tag under chin by pulling up and over your head.



2. Hold the power button for three seconds to turn off the device.



3. Unfasten the belt and remove.

**Wash your hands thoroughly before and after doffing. Your unit should be cleaned and stored according to the manufacturer's instructions.**